

# BACKFLOW DOUBLE CHECK ASSEMBLIES

As of May 1<sup>st</sup> 2018

**Removal of the Cross Connection Control Manual**, published by the Pacific Northwest Section of the American Water Works Association (AWWA) from IDPA 07.02.04.012.01.

All backflow requirements will be enforced from the Idaho State Plumbing Code (ISPC). The major change is double check backflow assemblies (DCBA), will no longer be allowed in lawn sprinkler applications. Any DCBAs installed prior to the code change will not need to be removed unless they can no longer be repaired. At that time, they will need to be upgraded with a Reduced Pressure Backflow Prevention Assembly (RPBP) or a Pressure Vacuum Breaker Assembly (PVB).

